



May 23, 2022

When installed on a Chevrolet 4500-6500 chassis, the remote start feature for the crane and accessories exhibits a delay of four to five minutes after shifting the truck from drive into park. There are two remedies for this issue rather than waiting the up to five minutes.

One option is to leave the key in the ignition in the “on” position.

The second option is to simply cycle the ignition. After shifting from drive to park, turn off the truck engine. Immediately restart the truck and turn off. This should allow the remote start for the crane to engage immediately.

Please contact us should you have any questions concerning this bulletin.

Respectfully,

Brian Welborn
Product Manager