



May 23, 2022

Please see the attached installation procedure provided by Boss Industries, Inc. The purpose of this dealer bulletin is to explain how to modify the harness of an Infinity 60 air compressor system to bypass an inoperable timer relay. The manufacturer of the timer relay has ceased production of the relay and replacement parts can no longer be provided.

Effective immediately, Auto Crane Part Number 755756000 is no longer available.

Thank you for your continued business. We remain dedicated to serving our dealer network for the mutual benefit of our shared customers and genuinely appreciate your dedication to the Auto Crane brand. Please contact us should you have any questions concerning this bulletin.

Respectfully,

Brian Welborn
Product Manager